# **EE491 Weekly Report 17**

Date: <u>2/20/17-2/26/17</u>

Group number: May 1717

Project title: 19 - Wireless Solar Temperature/Humidity Sensor

Client: Dan Stieler

*Team Members/Role:* 

Yi Qiu - General Member

Xiang Li - Webmaster

Kebei Wang - Team Leader

Trevor Brown - Key Concept Holder

Kukjin Chung - Communication Leader

**Weekly Summary** 

- Figured out drawing the schematic and pcb in eagle design tool.
- Figured out how to combine the functions together by coding.

## Past week accomplishments (please describe as what was done, by whom, when)

- Kebei W. learn how to use Eagle. Assist to design the PCB in new software tool-EAGLE.
- Yi Q. try to combine the functions together.
- Kukjin C. Schedule a meeting time. Try to combine the functions together.
- Trevor B. learn how to use Eagle. Assist to design the PCB in new software tool-EAGLE.
- Xiang L. Write the weekly report, and do some research about the problem we have in the project.

#### Pending Issues

- Learn new design tool.
- Combine the function together by coding.

#### <u>Individual contributions</u>

NAME	<u>Individual Contributions</u>	<u>Hours</u>	<u>HOURS</u>
		<u>this</u>	<u>cumulative</u>
		<u>week</u>	
Yi Qiu	try to combine the functions together. Group	4	59.5
	meeting.		
Xiang Li	Write the weekly report, and do some research	4	59.5
	about the problem we have in the project. Group		
	meeting.		
Kebei	learn how to use Eagle. Assist to design the PCB in	4	59.5
Wang	new software tool-EAGLE. Group meeting.		
Trevor	learn how to use Eagle. Assist to design the PCB in	4	59.5
Brown	new software tool-EAGLE. Group meeting.		
Kukjin	Schedule a meeting time. Try to combine the	4	59.5
Chung	functions together. Group meeting.		

Comments and extended discussion

None

### Plan for coming week (please describe as what, who, when)

- Kebei W. learn how to use Eagle to draw some complicated electrical components in schematic . Assist to design the PCB in new software tool-EAGLE.
- Yi Q. keep debugging and combining the functions together.
- Kukjin C. Schedule a meeting time. keep debugging and combining the functions together.
- Trevor B. learn how to use Eagle to draw some complicated electrical components in schematic . Assist to design the PCB in new software tool-EAGLE.
- Xiang L. Write the weekly report, and do some research about the problem we have in the project and help to solve the problem.